

# **Previous DM1000VCM Firmware** **version information**

## **DM1000VCM Firmware V2.40 for Win/Mac OSX**

### **Fixed Bug**

- Fixed a problem that when the DM1000 was used with an MY8-AE96(S) inserted to the slot and a certain channel input signal was unlocked or failed in synchronization, noise was generated to another channel input signal.