

# **Previous MMP1 Firmware version information**

## **V1.02-2 to V1.10**

### **New Features in V1.02-2**

- Now supports Dante Domain Manager.  
Update the Dante Firmware to V4.0.8.2. Use “FWUpdate\_MMP1\_v40082\_sw206.dnt” in the compressed file (.zip) for updating.

### **Information**

- When you initialize the MMP1 enrolled in the Dante Domain to the factory programmed settings, clear Domain information in the Dante module according to the instructions on the following website, and then execute the initialization using DIP switch of the device.  
[https://dev.audinate.com/GA/dante-controller/userguide/webhelp/#ddm\\_domain\\_credentials.htm](https://dev.audinate.com/GA/dante-controller/userguide/webhelp/#ddm_domain_credentials.htm)

## **V1.00 to V1.02**

### **Fixed bug**

- Solved a problem in which the port for which “Pulse” is selected on the “Behavior” of the “GPI Out” setting may not have worked properly.